



Paul's Product Review

'84 - '88 Door Water Shields & Door Panel Jute Insulation

by: Paul Vargyas



The Fiero Store (www.fierostore.com) has introduced two new products that will help extend the life of your doors from corrosion and help reduce noise. All of us have had the situation of working on the doors to lubricate tracks or PW/PDL components and in the process removed or destroyed the water shield and insulation. These two products will help to prevent additional moisture damage as well as help insulate the door from road noise.

1984-1988 Door Water Shields (pair) #57661

These mylar water shields fit up against the door shell and keep moisture out of your interior. Note: These originally came installed underneath all of the door bracketry. The correct way to install them would be to drill out all of the rivets holding the brackets to the door, install the shields and then reinstall the brackets. Or, they can easily be mounted without removing brackets, but this will require some trimming to clear any brackets. Use of silicon sealant for installation will result in a true water seal. These install with butyl tape or silicon sealant, not included. The cost is \$22.94 (pair); even less with your NIFE club discount!

1984-1988 Door Panel Jute Insulation (pair) #57660

This jute insulation fits in between the door shell and the interior door panel. It is designed to keep noise and cold drafts out of the interior. With most Fieros being over 25 years old, insulation is missing, torn or soaked with years of water from weatherstripping leaks. The Fiero Store recommends using 3M weatherstrip adhesive for installation (see part #51417), not included. The cost is \$24.95 (pair); even less with your NIFE club discount!